

Spur	Hersteller	Artikelnr	Von	Bis	Baureihe	Verwaltung	Lok Nr.	Motor	H3D Umbausatz	Verwendete Motor
00	Airfix	54051-5	1976	1981	4-4-0		Jupiter			
00	Airfix	54052-3	1976	1981	Class 31	BR	D5531		in Entwicklung	
00	Airfix	54053-1	1976	1981	4-4-0	Union Pacific	119			
00	Airfix	54054-4	1976	1981	Class 31	BR	31401		in Entwicklung	
00	Airfix	54055-7	1976	1981	Class 31	BR	D5531		in Entwicklung	
00	Airfix	54056-0	1976	1981	Prairie 2-6-2T	GWR	6110		in Entwicklung	
00	Airfix	54057-3	1976	1981	Prairie 2-6-2T	BR	6167		in Entwicklung	
00	Airfix	54058-6	1977	1981	Royal Scot	LMS	6103		0A001	2607S
00	Airfix	54059-9	1977	1981	4F Fowler	LMS	4454		0A001	2607S
00	Airfix	54063-8	1980	1981	Class 31	BR	D5531		in Entwicklung	
00	Airfix	54067-0	1980	1981	Prairie 2-6-2T	BR	6167		in Entwicklung	
00	Airfix	54068-3	1980	1981	Royal Scot	LMS	6103		0A001	2607S
00	Airfix	54069-6	1980	1981	Castle class	GWR	4073 Caerphilly Castle		0A001	2607S
00	Airfix	54100-6	1976	1981	Class 31	BR	31401		in Entwicklung	
00	Airfix	54101-9	1976	1981	Class 31	BR	D5531		in Entwicklung	
00	Airfix	54120-0	1977	1981	Royal Scot	LMS	6103		0A001	2607S
00	Airfix	54121-3	1977	1981	Royal Scot	BR	46100		0A001	2607S
00	Airfix	54122-6	1977	1981	4F Fowler	LMS	4454		0A001	2607S
00	Airfix	54123-9	1977	1981	4F Fowler	BR	44454		0A001	2607S
00	Airfix	54124-2	1980	1981	Castle class	GWR	4073 Caerphilly Castle		0A001	2607S
00	Airfix	54125-5	1980	1981	Castle class	BR	Pendennis Castle		0A001	2607S
00	Airfix	54150-1	1976	1981	Prairie 2-6-2T	GWR	6110		in Entwicklung	
00	Airfix	54151-4	1976	1981	Prairie 2-6-2T	BR	6167		in Entwicklung	
00	Airfix	54152-7	1980	1981	14XX Tank	GWR	1466		in Entwicklung	
00	Airfix	54153-0	1980	1981	14XX Tank	BR	1466		in Entwicklung	
00	Airfix	54170-5	1976	1981	4-4-0		Jupiter			
00	Airfix	54171-8	1976	1981	4-4-0	Union Pacific	119			